

FACILITY NAME: <i>Whonnock Lake Park Water System</i>		INSPECTION DATE (yyyy/mm/dd): <i>2024/June/14</i>	TIME SPENT: <i>1.0</i>
FACILITY ADDRESS: <i>27871 - 113 Ave, Maple Ridge</i>		NEXT INSPECTION DATE (yyyy/mm/dd): <i>2025/June/15</i>	
☐ NEW PERSON IN CHARGE: <i>Michael Albrecht</i>		☐ New Tel: (<i>604-363-6671</i>) ☐ New Fax: ()	
☐ NEW EMERGENCY CONTACT: <i>City of Maple Ridge</i>		☐ New Tel: () ☐ New Fax: ()	
FACILITY TYPE: ☐ WS1 (300+ connections) ☐ WS4 (1 public connection) ☐ WS2 (15 - 300 connections) ☐ WS9 (other) ☒ WS3 (2 - 14 connections)		INSPECTION TYPE: ☐ Initial ☐ Consultation ☐ Follow Up to Lab Report ☒ Routine ☐ Sampling ☐ Water Quality Complaint ☐ Follow Up ☐ Investigation ☐ Water Borne Illness Complaint	
ACTION TAKEN: ADMINISTRATIVE ☒ Information Provided ☐ No Action Required ☐ Permit Issued ☐ Rescind Public Notification		OTHER INFORMATION: (complete for Routine Inspection) EOCB (operator certification) ☒ Yes ☐ No ☒ N/A Acceptable SWS Training ☒ Yes ☐ No ☐ N/A ERCB (emergency plan) ☒ Yes ☐ No ☐ N/A Annual Report Provided to Users ☒ Yes ☐ No ☐ N/A	

HAZARD RATING FOR YOUR FACILITY: ☐ High ☐ Moderate ☒ Low

Follow Up to "Critical" Violations Noted on Previous Inspections (if applicable)

Code	Corrected?	Code	Corrected?
	☐ Yes ☐ No		☐ Yes ☐ No
	☐ Yes ☐ No		☐ Yes ☐ No
	☐ Yes ☐ No		☐ Yes ☐ No

Code	Explanation of Violations, Recommendations or Comments	(✓) Corrected During Insp.	Date To Be Corrected By
	<i>Treatment system maintained</i> <i>- UV unit maintained - 1x/yr.</i> <i>- Carbon, 1um, 5um filters - 3 months</i>		<i>filter change triggered pressure differential 60-70</i>
	<i>Review & updating of ERCP discussed</i>		
	<i>Chemical & physical health-based parameters analysed May 29, 2024 and are in compliance with health guidelines</i>		
	<i>Bacteriological water quality & sampling frequency is in compliance.</i>		

RECEIVED BY (Signature): <i>Michael Albrecht</i>	EHO (Signature): <i>Heather Stolt</i>
PRINTED NAME: <i>Michael Albrecht</i>	EHO PRINTED NAME: <i>Heather Stolt</i>