fraserhealth

DRINKING WATER INSPECTION REPORT
Health Protection
BSIA-DMULVU

PREMISES NAME	Tel: (604) 463-9581 Fax: (604) 467-7360	
Whonnock Community Well Water System		
PREMISES ADDRESS 10875 272nd St Maple Ridge, BC	INSPECTION DATE October 22, 2025	TIME SPENT 0.75 hours
OPERATOR (Person in Charge) Mike Gjaltema	NEXT INSPECTION DATE 12 Months	

FACILITY TYPE

☐ WS1 (300+ connections) ☒ WS4 (1 public connection)
☐ WS2 (15-300 connections) ☐ WS9 (other)
☐ WS3 (2-14 connections)

INSPECTION TYPE

☐ Initial	☐ Sampling	☐ Water Borne Illness Complaint
☒ Routine	☐ Investigation	☐ Follow-Up to Complaint/Referral
☐ Follow-Up	☐ Follow-Up to Lab Report	
☐ Consultation	☐ Water Quality Complaint	

ACTION TAKEN

ADMINISTRATIVE
☒ Information Provided
☐ No Action Required
☐ Permit Issued
☐ Rescind Public Notification

ENFORCEMENT
☐ Require Corrections ☐ Written Order
☐ Ticket Issued ☐ Order Public Notification

OTHER INFORMATION:

(complete for Routine Inspection)

	Comply
EOCP (operator certification)	Yes
Acceptable SWS Training	Yes
ERCP (emergency plan)	Yes
Annual Report Provided to Users	Yes

HAZARD RATING FOR YOUR FACILITY: ☐ High ☐ Moderate ☒ Low Total Score = 0

Critical Hazards: There are no critical hazards.

Non-Critical Hazards: There are no non-critical hazards.

Follow Up to "Critical" Violations Noted on Previous Inspections (if applicable): No corrections entered

Comments

- Sampling is being done as required through Metro Vancouver Lab. The results are satisfactory.
- Storage tank is chlorinated quarterly by the City of Maple Ridge utilities staff.
- UV light is maintained, bulb is replaced annually. Operator are planning on replacing the UV light system in the near future.
- Water fill line is equipped with RP backflow valve and it is checked annually.
- Operation and maintenance logs are maintained.

No concerns at this time.

RECEIVED BY	EHO
PRINTED NAME **Ron Thom**	EHO PRINTED NAME **Binny Sivia**