DRINKING WATER INSPECTION REPORT
Health Protection
BSIA-DMULRM

PREMISES NAME Whonnock Lake Park WS	Tel: (604) 466-4342 Fax: (604) 467-7360	
PREMISES ADDRESS 27871 113th Ave Maple Ridge, BC V2W 1M9	INSPECTION DATE October 22, 2025	TIME SPENT 0.75 hours
OPERATOR (Person in Charge) Michael Albrecht	NEXT INSPECTION DATE 12 Months	

FACILITY TYPE

- ☐ WS1 (300+ connections)
- ☐ WS2 (15-300 connections)
- ☒ WS3 (2-14 connections)
- ☐ WS4 (1 public connection)
- ☐ WS9 (other)

INSPECTION TYPE

- ☐ Initial
- ☒ Routine
- ☐ Follow-Up
- ☐ Consultation
- ☐ Sampling
- ☐ Investigation
- ☐ Follow-Up to Lab Report
- ☐ Water Quality Complaint
- ☐ Water Borne Illness Complaint
- ☐ Follow-Up to Complaint/Referral

ACTION TAKEN

ADMINISTRATIVE

- ☒ Information Provided
- ☐ No Action Required
- ☐ Permit Issued
- ☐ Rescind Public Notification

ENFORCEMENT

- ☐ Require Corrections
- ☐ Ticket Issued
- ☐ Written Order
- ☐ Order Public Notification

OTHER INFORMATION:

(complete for Routine Inspection)

	Comply
EOCP (operator certification)	Yes
Acceptable SWS Training	Yes
ERCP (emergency plan)	Yes
Annual Report Provided to Users	Yes

HAZARD RATING FOR YOUR FACILITY: ☐ High ☐ Moderate ☒ Low Total Score = 0

Critical Hazards: There are no critical hazards.

Non-Critical Hazards: There are no non-critical hazards.

Follow Up to "Critical" Violations Noted on Previous Inspections (if applicable): No corrections entered

Comments

- Sampling is done as required through the Metro Vancouver Lab. Results are satisfactory.
- Well is in good condition. Holes have been drilled in the outer box to prevent water from pooling around the well head.
- Treatment system is well maintained. Filters and UV light bulb is replaced as required.
- System is equipped with automatic flush valve during low usage periods.
- Emergency response plan is up to date.
- Annual report is available on the City of Maple Ridge Website.

No concerns at this time.

RECEIVED BY	EHO
PRINTED NAME **Ron Thom**	EHO PRINTED NAME **Binny Sivia**